

November 12, 2021

Via Email/Sharefile

Ms. Julia Galayda
Bureau of Case Management
New Jersey Department of Environmental Protection
401 East State Street
PO Box 28
Trenton, New Jersey 08625-0028

Re: Summary of Tankfield 3 Incident & Response
Hess Corporation Former Port Reading Complex (HC-PR)
750 Cliff Road
Woodbridge, Middlesex County, New Jersey
NJDEP PI# 006148
ISRA Case No. E20130449
EPA ID No. NJD045445483

Dear Ms. Galayda:

On February 24, 2021, Buckeye Partners, LLC (Buckeye) observed the presence of liquid-phase hydrocarbon (LPH) on the ground surface in Tankfield 3, near tank 1216. The following is a brief summary of the incident and subsequent response activities, which included groundwater sampling and data collection.

As per the Industrial Site Recovery Act (ISRA) requirements, a Preliminary Assessment (PA) was conducted in 2015 and Tankfield 3 was identified as Area of Concern (AOC) 54. Tankfield 3 is a lined tankfield surrounded by berms and currently consists of 9 active tanks (numbered as 1215 through 1223 and 7945) (see **Figure 1**). The liner consists of a geosynthetic clay liner topped with: a non-woven geotextile, fine recycled concrete aggregate layer (6 inches thick), and then a surficial layer of stone (6-12 inches thick depending on location).

Description of Incident and Response:

As noted above, the presence of LPH was observed on the ground surface in Tankfield 3 on February 24, 2021 by Buckeye. Concurrently with this observation, there was also an incident reported by Buckeye to the National Response Center (NRC) regarding Tank 1219 (also present in Tankfield 3).

The following records were located using NJDEP Dataminer:

Spill #21-02-25-0810-17, Date 2/25/2021 (Linked Incident 782332)

Description – "Caller is reporting gasoline tank #1219 has a tilted roof which may create a potential for odor complaints in the area"

Spill #21-03-01-0852-47, Date 3/01/2021 (Linked Incident 782493)

Description – "NRC received via Comm Center stating – Caller is reporting a discharge of an estimated 50 barrels of a water and gasoline mixture from a storage tank due to a problem with the floating roof. The material is in the containment area. Material spilled into second containment; the material is being pumped out at this time. On scene point of contact Brandon Leehan 732-966-3635."

Buckeye has provided Hess/Earth Systems copies of all correspondence relating to the above incidents and all provided documentation is included as an attachment to this letter (**Attachment A**).

In response to the observed LPH in Tankfield 3, Buckeye initially retained Atlantic Response to address the issue via the use of absorbent booms and vacuum extraction.

Tankfield 3 Earth Systems/Hess Response Activities

Buckeye personnel reported the presence of LPH to Hess Corporation (Hess) and Earth Systems on February 24, 2021. Earth Systems personnel immediately mobilized to the Site to inspect the area with Buckeye on the same day.

On February 25, 2021, Earth Systems observed two (2) different types of product-like material in Tankfield 3: a liquid and a more viscous, more solid -type of material. Samples were collected of both types of material and sent to SGS Laboratory (SGS) for fingerprint analysis. The liquid sample was estimated to be approximately 60-70% oil layer on top of an aqueous layer. The analysis was conducted on the oil phase only. Due to the chemical complexity of refined petroleum products, SGS utilizes a library of typical chemical analytes to compare to unknown source materials. The liquid substance was a match for gasoline and motor oil and there was no product match for the viscous sample. Laboratory reports are included in **Attachment B**.

Earth Systems, on behalf of Hess, assumed monitoring and mitigation efforts on February 26, 2021. Earth Systems retained AWT Environmental Services to provide remediation services during the response to this incident. On February 27, 2021, AWT replaced the booms initially deployed by Atlantic Response.

Following the incident, Earth Systems monitored Tankfield 3 several times a week and after rain events. LPH has not been observed at the surface of Tankfield 3 since March 3, 2021. An inspection log is included in **Attachment C**.

A total of two (2) drums of spent sorbent booms and pads were generated and disposed of offsite. Disposal manifests are included in **Attachment D**.

Groundwater Monitoring

During the 2015 Site Investigation (SI), three (3) groundwater monitoring wells were installed in Tankfield 3 and groundwater samples are typically collected on an annual basis in November/December.

As part of the response to this incident, groundwater samples were collected from the Tankfield 3 monitoring wells on March 25, 2021. The monitoring wells are located adjacent to the location of the observed LPH. The monitoring wells were gauged prior to sampling and no product was detected in the wells. Benzene was detected at a concentration of 82.8 parts per billion (ppb) in the groundwater sample collected from monitoring well TF-2, which is a higher concentration than detected historically in this well. In addition, ethyl benzene, toluene, and xylenes were also detected in the groundwater sample collected from this well at concentrations significantly higher than historic results. A summary table of the groundwater results is included below. The location of the monitoring wells and the analytical results are summarized on **Figure 2**. Laboratory reports are included in **Attachment B**.

Well ID Sample Date								
		Benzene	Ethylbenzene	Toluene	Xylenes			
GW	/QS	1	700	600	1000			
TF-1	TF-1 11/27/2018		ND (0.60)	ND (0.53)	1.5			
TF-1	11/7/2019	0.69	ND (0.60)	ND (0.53)	1.7			
TF-1	12/11/2020	ND (0.43)	ND (0.60)	ND (0.53)	ND (0.59)			
TF-1	3/25/2021	ND (0.43)	ND (0.60)	ND (0.53)	ND (0.59)			
TF-2	11/27/2018	NS	NS	NS	NS			
TF-2	11/7/2019	1.3	ND (0.60)	ND (0.53)	0.70 J			
TF-2	12/11/2020	NS	NS	NS	NS			
TF-2	3/25/2021	82.8	96.2	698	628			
TF-3	11/27/2018	6.5	ND (0.60)	ND (0.53)	ND (0.59)			
TF-3	11/7/2019	2.8	ND (0.60)	ND (0.53)	ND (0.59)			
TF-3	12/11/2020	ND (0.43)	ND (0.60)	ND (0.53)	ND (0.59)			
TF-3 3/25/2021 16		16.1	ND (0.60)	4.5	ND (0.59)			
MDL - Method D	MDL - Method Detection Limit, ND - Non-Detect (MDL), NS - Not Sampled due to LNAPL sheen							

The Tankfield 3 monitoring wells were gauged in April, on a biweekly basis, and a discontinuous layer of product was observed in monitoring well TF-2. There was not a sufficient amount of product present to measure with a probe. A sample of the product/groundwater was collected on April 23, 2021 and sent to SGS for fingerprint analysis. The product/groundwater sample was a match for diesel/fuel oil #2 (C9-C22) and motor oil. Please note that the product sample results collected from the tankfield

surface in February 2021 identified the product match as gasoline and motor oil, which differs from the April 2021 fingerprinting results.

The laboratory report is included in **Attachment B**.

Impacted Stone Remediation

On August 18, 2021, AWT Environmental Services, under the oversight of Earth Systems, excavated and disposed of approximately eighteen (18) tons of visually impacted stone from Tankfield 3 and subsequently backfilled the area with certified clean stone. The following section provides a summary of these remediation activities.

Earth Systems conducted an inspection of the LPH impacted area in Tankfield 3 and observed an isolated area of visually stained stone at the surface of the tankfield. On August 18, 2021, all visually impacted stone was excavated. The excavated area measured approximately 1,750 square feet (see **Figure 2**). The impacted stone was excavated using a small track skid steer and hand tools (shovels and rakes) to a maximum depth of approximately 2-inches. Visually impacted stone was only observed at the surface and a non-impacted layer of stone was encountered at the base of the excavation activities. No excavation activities extended into or breached the tankfield liner. An estimated eighteen (18) tons of impacted stone was removed for off-site disposal at a licensed facility. Disposal manifests are included in **Attachment D**. Following stone removal, the area was backfilled with certified clean ³/₄-inch gravel. Certified clean fill documentation is included in **Attachment E**.

Photographs of the stone remediation activities are included in **Attachment F**.

Prior to stone removal, samples were collected for waste class purposes on June 25, 2021. The waste class laboratory analytical results are included in **Attachment B**.

Conclusions/Recommendations:

Cleanup activities were conducted by Buckeye (and their contractors) and Earth Systems (on behalf of Hess) in response to the surface LPH incident in Tankfield 3. No LPH has been observed on the surface of Tankfield 3 since March 3, 2021 and all impacted surface stone was excavated in August 2021. Based on field observations during the stone removal, it appears that all impacts were present at the surface only. This indicates that the source of the incident was due to a surficial release and not due to an issue with the tankfield liner. No additional remediation activities are recommended regarding this incident.

A Remedial Investigation Workplan (RIW) for all the complex's tankfields was submitted to NJDEP on May 10, 2021. The RIW includes recommendations for additional soil and groundwater investigation activities in Tankfield 3.

Regarding the two (2) spill cases referenced in the "Description of Incident and Response" section pertaining to the Buckeye incident with AST 1219, these cases will need to be managed and closed by Buckeye and are not the responsibility of Hess.

Should you have any questions or require additional clarification or information, please contact me at 732-739-6444 or via e-mail at ablake@earthsys.net. If you have any questions relating to the project, you can also contact Mr. John Schenkewitz of Hess Corporation at 609-406-3969 or jschenkewitz@hess.com.

Sincerely,

Amy Blake

Sr. Project Manager

Mr. Sameh Abdellatif – EPA (via email/Sharefile) C.


Mr. John Schenkewitz – Hess Corporation (via e-mail)


Ms. Krista Manley - Buckeye (via e-mail)

Mr. Rick Ofsanko – Earth Systems (via e-mail)

Mr. John Virgie – Earth Systems (via e-mail)

Mr. Frank Sanclementi – Earth Systems (via e-mail)





Attachment A



BUCKEYE PORT READING TERMINAL. LLC

Five Tek Park 9999 Hamilton Blvd. Breinigsville, PA 18031 Tel (610) 904-4000 Fax (610) 904-4549

May 28, 2021 Bureau of Release Prevention New Jersey department of Environmental Protection 401 East State St Trenton, NJ 08625

MEMORANDUM

SUBJECT: BUCKEYE PORT READING TERMINAL

NON-REPORTABLE RELEASE NJDEP Case # 21-03-01-0852-47

To whom it May Concern,

The following information has been provided for your file and information:

At approximately 0630 on 3/1/2021, an Operator conducting rounds at Port Reading identified a sheen in the tank dike adjacent to TK 1219. This tank was in the process of being completely emptied because of an external floating roof issue. The tank was stripped out of free product (tank was in premium gasoline service) and over the weekend the tank was being monitored to allow for ice to melt so that the remaining product/water mixture could be removed. The release point appeared to be coming from the chime of the tank. It was estimated that approximately 50 bbls of product/water mixture was released from the tank. The product/water mixture was contained within dike containment and no product/water mix has migrated off site. The Tank is USDOT PHMSA jurisdictional Tank.

Enclosed is a summary of field observations made at Tank 1219 on March 31, 2021 and April 5, 2021 by Buckeye's LSRP.

The release is not a NJDEP reportable release.

If You have any questions, please do not hesitate to contact me at 732-754-6672.

Regards,

Monika Niedbala

Moules Madel

HSSE Sr.Specialist Buckeye Port reading Terminal 750 Cliff Rd Port Reading, NJ 07064



750 Cliff Road Port Reading, NJ 07064

March 18, 2021

Mr. Chris Odgers
New Jersey Department of Environmental Protection
Bureau of Air Compliance & Enforcement – Central Regional Office
Mail Code 22-03A
401 East State Street
P.O. Box 420
Trenton, New Jersey 08625-0420

Re: Tank 1219 Floating Roof Repair and 7-Day Refill Notification Buckeye Port Reading Terminal, LLC (PIN 17996)

Dear Mr. Odgers,

In accordance with the reporting and record keeping requirements of NESHAPS Subpart 6B referencing 40 CFR Part 60.113b (a) (5), Buckeye is providing this floating roof tank refill notification. The facility is submitting a 7-day tank refill notice for an unplanned repair and roof inspection for Tank 1219 at the Buckeye Port Reading Terminal. The tank is expected to be refilled in early April. If you have any questions, please contact Fran Lindsley-Matthews at 732-738-2065 or at flindsley-matthews@buckeye.com.

Sincerely,

Ed Buchalski

Ed Buchalski Senior Operations Manager

VIA CERTIFIED MAIL – RETURN RECEIPT REQUESTED 7016 0910 0000 5302 5287

Cc by Certified Mail 7016 0910 0000 5302 5300 to:

United States Environmental Protection Agency, Region II, Air Compliance Branch, 290 Broadway, New York, New York 10007-1866

Cc by Email to:

F. Lindsley-Matthews, M. Boylan, M. Niedbala

Direct Knowledge Official Signature Statement

Pursuant to N.J.A.C. 7:27-1.39(a)1: "I certify, under penalty of law, that I believe the information provided in this document is true, accurate and complete. I am aware that there are significant civil and criminal penalties, including the possibility of fine or imprisonment or both, for submitting false, inaccurate or incomplete information."

te: <u>3/16/21</u>
ir Compliance

Responsible Official Signature Statement

Telephone: 732-738-2065

Pursuant to N.J.A.C. 7:27-1.39(a)2: "I certify, under penalty of law, that I have personally examined and am familiar with the information submitted in this document and all attached documents and, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant civil criminal penalties, including the possibility of fine or imprisonment or both, for submitting false, inaccurate or incomplete information."

Signature: Br & Operations manager on behalf of Ed Date: 3/18/21

Print: Ed Buchalski

Title of Responsible Official: Senior Operations Manager

Telephone: 347-452-8816

T: 856.330.9400 F: 856.330.9401



April 26, 2021

Ms. Monika Niedbala Buckeye Port Reading Terminals, LLC HSSE Compliance - Environmental, East Region - Northeast Area 750 Cliff Road Port Reading, NJ 07064

Subject: Tank 1219 – Field Observations Buckeye Port Reading Terminal Port Reading, New Jersey

Dear Ms. Niedbala:

Brown and Caldwell (BC), on behalf of Buckeye Port Reading Terminals, LLC (Buckeye), has prepared this letter report to summarize field observations made at Tank 1219 on March 31, 2021 and April 5, 2021. Tank 1219 is a steel, 2,258,256 million gallon, gasoline aboveground storage tank, constructed in 1960 The tank is located in the third tank field containment area with Tanks 1215 through 1223. A secondary containment liner system was installed in the third tank field in 2020

On March 31, 2021, Mr. Scott Nelson, P.E., LSRP of Brown and Caldwell (BC) visited the site to meet with Buckeye and to inspect the tank and containment area to confirm that a recent release has not impacted groundwater and therefore can be defined as a leak. Residual product and or stormwater was not observed in the tank field containment area and product was not present around the edges of the tank. The area was dry and no visual impacts or odors were present. BC was prepared to collect soil samples from below the tank to determine if product and/or impacted soil was present below the floor. With the assistance of Atlantic Response, under Confined Space Entry protocol, it was determined that soil samples could not be collected due to concrete that was present directly below the hole in the tank bottom.

In order to determine if concrete is present below other areas of the tank bottom, Buckeye installed a second hole in the tank bottom on April 5, 2021. Mr. Scott Nelson, P.E., LSRP of BC was present on April 5, 2021 to inspect the tank bottom and to collect soil samples from below the tank, if possible. With the assistance of Atlantic Response, under Confined Space Entry protocol, it was determined that concrete was present below the second hole in the tank bottom and therefore, soil samples could not be collected.

Ms. Monika Niedbala Buckeye Port Reading Terminals, LLC April 26, 2021 Page 2

Based on the information presented in this letter, and the findings of the March 31, 2021 and April 5, 2021 site inspections, the gasoline released into the tank field containment area did not migrate into the subsurface below the tank due to the concrete present below the tank. The gasoline that was released was contained within the tank field containment area due to the liner system and was immediately recovered by Atlantic Response. BC recommends no further action with respect to Tank 1219.

Very truly yours,

Brown and Caldwell

Scott Nelson, PE, LSRP Brown and Caldwell

cc: Krista Manley, Buckeye Port Reading Terminal, LLC

Attachment B (See Separate Electronic File)

Attachment C

ATTACHMENT - C Tankfield 3 Inspection Log						
Date	Tankfield 3 Inspection Time	Notes/Comments				
3/8/2021	11:00am	No LPH or sheen observed.				
3/10/2021	1:15pm	No LPH or sheen observed.				
3/11/2021	1:45pm	No LPH or sheen observed.				
3/12/2021	1:30pm	No LPH or sheen observed.				
3/15/2021	2:05pm	No LPH or sheen observed.				
3/16/2021	11:00am	No LPH or sheen observed.				
3/18/2021	10:30am	No LPH or sheen observed.				
3/19/2021	12:15pm	Raining during inspection event. No LPH or sheen observed.				
3/22/2021	12:30pm	No LPH or sheen observed.				
3/23/2021	12:20pm	No LPH or sheen observed.				
3/24/2021	12:20pm	No LPH or sheen observed.				
3/25/2021	10:30am	Rained the prior day/evening. No LPH or sheen observed.				
		No LPH or sheen observed.				
3/26/2021	1:45pm					
3/29/2021	12:45pm	No LPH or sheen observed.				
3/30/2021	9:30am	No LPH or sheen observed.				
3/31/2021	1:00pm	No LPH or sheen observed.				
4/1/2021	1:00pm	Rained the prior day/evening. No LPH or sheen observed.				
4/2/2021	4:09pm	No LPH or sheen observed.				
4/5/2021	3:15pm	No LPH or sheen observed.				
4/6/2021	8:00am	No LPH or sheen observed.				
4/7/2021	10:30am	No LPH or sheen observed.				
4/8/2021	2:40pm	No LPH or sheen observed.				
4/9/2021	10:50am	No LPH or sheen observed.				
4/12/2021	11:15am	Rained the prior day/raining during site inspection. No LPH or sheen observed.				
4/13/2021	4:26pm	No LPH or sheen observed.				
4/14/2021	11:30am	No LPH or sheen observed.				
4/15/2021	1:45pm	Raining during site inspection. No LPH or sheen observed.				
4/16/2021	10:25am	No LPH or sheen observed.				
4/19/2021	1:20pm	No LPH or sheen observed.				
	· · · · · · · · · · · · · · · · · · ·					
4/21/2021	10:00am	No LPH or sheen observed.				
4/22/2021	10:45am	Thunderstorms/rain over past 24 hrs., no precipitation during site visit. No LPH or sheen observed.				
4/23/2021	11:24am	No LPH or sheen observed.				
4/26/2021	10:00am	Rained the prior day. No LPH or sheen observed.				
4/27/2021	10:15am	No LPH or sheen observed.				
4/28/2021	1:43pm	No LPH or sheen observed.				
4/30/2021	9:15am	Rained the prior day. No LPH or sheens observed.				
5/3/2021	1:10pm	No LPH or sheen observed.				
5/4/2021	10:48am	Rained the prior evening. No LPH or sheen observed.				
5/5/2021	11:45am	Rained the prior evening. Cloudy during site visit. No LPH or sheen observed.				
5/6/2021	10:21am	Intermittent light rain showers the previous afternoon and evening. No LPH or sheen observed.				
5/7/2021	11:05am	No LPH or sheen observed.				
5/10/2021	2:45pm	Rain the prior evening. No LPH or sheen observed.				
5/12/2021	9:30am	Rain the prior evening. No LPH or sheen observed.				
5/14/2021	10:20am	No LPH or sheen observed.				
5/19/2021	10:30am	All booms were removed by Buckeye on 5/18/21. No LPH or sheen observed.				
		No LPH or sheen observed.				
5/21/2021	10:30am					
5/24/2021	1:00pm	No LPH or sheen observed.				
5/26/2021	10:29am	No LPH or sheen observed.				
5/27/2021	11:49am	No LPH or sheen observed.				
5/28/2021	11:01am	No LPH or sheen observed.				
6/1/2021	11:00am	No LPH or sheen observed.				
6/4/2021	12:30pm	Intermittent thunderstorms. No LPH or sheen observed.				
6/9/2021	11:30am	Thunderstorms the prior afternoon and evening. No LPH or sheen observed.				
6/11/2021	8:15:am	No LPH or sheen observed.				
6/17/2021	11:04am	No LPH or sheen observed.				

Attachment D

WELDON MATERIALS, INC.

TECHNICAL SERVICES

141 CENTRAL AVENUE, WESTFIELD, NJ 07090 (908) 233-4444 ext. 2288 FAX (908) 233-4215 email: rarocha@weldonmat.com

July 27, 2021

MADDOX MATERIALS, LLC

Email / Fax: email Attn: Bill Maddox Jr

Reference: Projects # 17620 and 17704

750 Cliff Road Port Reading, NJ

Material: 1 1/2" and 3/4" CRUSHED STONE

To whom it may concern:

We certify that the aggregates to be purchased for the project in reference are produced by Fanwood Crushed Stone Company established and mining since 1907, from sources of virgin basalt indigenous to the region. These aggregates are free from contamination, and have not been subject to a discharged hazardous substance at any time; when produced, and stockpiled at our quarry in Watchung, NJ

Our Quarry is located at:

#1 New Providence Road

Watchung, NJ Somerset County.

Block #: 7601, Lots #: 4, 5, 6, 13, 19, 20, 25, 26, 27, and 28

Mine Certificate #: 004840

Sincerely,

RICARDO AROCHA TECHNICAL SERVICES

Attachment E

Straight Bill of Lading

PIE	ise type or pr	int											
	1. Generator EPA ID # (if applicable)		licable)	2. Page 1 of	3. Emerge	ncy Response		4. Document Tracking Number					
	ENV	IRO	NJD045445483		2	908-354	-0210	ACI	/ 0862	086223			
	5. Generato	r Name and Mailir	ng Address			Generator's	s Site Address	(if different)					
								,					
			DING TERMINAL				HESS PC	ORT READING 1	ΓERMINAL ((COMP	PANY	CC	
		ACK STEPH TTRENTON					750 CLIF	F KOAD EADING, NJ 070	164				
								LADING, NJ 070	/O ·1				
	Generator Phone: 610-390-4172 6. Transporter 1 Company Name ACV ENVIRONMENTAL SERVICES, INC				US EPA ID Number (if applicable) NJD003812047								
) 									
	7. Transpor	ter 2 Company Na	me		US EPA ID Number (if applicable)								
	8. Designat	ed Facility Name a	and Mailing Address			US EPA	ID Number (if	applicable)					
	CYCL	E CHEM, INC	0										
	217 S	OUTH FIRS	Γ STREET					NJD00220	00046				
	ELIZA	BETH, NJ 07	7206										
<u>_</u>			000 055 5000										
atc		ed Facility Phone:	908-355-5800										
Je.	9a. HM	(Proper	9b. Material Descrip shipping name required if DOT			10. Contain		11. Total Quant	tity 12. U		13 Was		
Generator	11111	1.		- Tazar acasa Materially		No.	Туре		(Wt/V	/01)	Cod		
			NON RCRA PETROL	EUM MIXTURE									
		SOLID			1	4/ 1	DM ³	100	/ P	,	27		
							DIVI	100			2.1		
		2.			F								
		NON DOT	NON RCRA REGULA	TED MATERIAL	L								
					1	XZ	DM	1300	/ P	3	27		
		3.				117		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-	-			
	NON REGULATED MATERIAL®												
				V	1 1	DM	701		,	72			
								1700					
		NON DOT	NON RCRA REGULA	TED MATERII A	Δ	115-1151							
		(SPENT CA		TO WITH EIGH			DM	× 1	P	,	27		
		(,			XX		100	11				
	14. Special	Handling Instructi	ons and Additional Information	D75000 00 70	1005	ET 050		100	0	_			
	, i			D75909 SO 78	385 LDR 0	in FileSES	5O#	STXL	Z				
	4\Drofil	-#90442 /M	040) #6 EHEL OIL OD	III DEBBIG A	\Dmafila#606	40 - ODEN	T DAO E	(TED A)Doction	#40004 (140	400			
	PETRO	SHOS 142 (IVI	010) #6 FUEL OIL SP TAMINATED WELL W	ILL DEDKIO Z)PTOTII0#030	40 SPEN	DBON	LIER 3)Profile	#42634 (MU	116)			
	1 LIIKO	LEON CON	I VIAILIAN LED AACTE AA	AIER 4/FIOII	18#03031 31	PENT CA	ROON						
	TO 11 - 17				111111111111111111111111111111111111111		111		T WILL	tion.			
	16. Genera	tor/Offeror's Certifi	cation: I hereby declare that the	e contents of this consi	ignment are fully	and accurately	v described at	bove by the proper ship	ning name and are	e classifie	ed.		
	packaged,	marked and labele	d/placarded and are in all respe	ects proper condition fo	or transport accor	ding to applica	able internatio	nal and national govern	mental regulations	S.	, ,		
	Printed/Type	ed Name	A 6.		Signature		s [.		1	vionth	Day	Year	
	X	Acom	of Itess		× CI	Tent.	of 11	E) [ĺ	131	08	21	
	17. Transpo	rter Acknowledg	ment of Receipt of Materials		Signature	0		•					
er	Printed/Type	Printed/Typed Name Month Day Year											
out	Mas Um					03/08					08	21	
Transporter	18. Transpo	rter 2 Acknowledg	ment of Receipt of Materials		Signature							7	
Tra	Printed/Type	ed Name			a				1 1	√lonth	Day	Year	
										ľ	1		
	19. Discrepa	ancy Indication Spa	ace (to be completed by Design	ated Facility)									
		,											
ity													
Facility	20 Discrens	ncy Facility: Corti	fication of receipt of the materia	le covered by this abin	ning paper ever	t as noted in i	tom 10						
ιĭ				to sovered by this ship	Signature	i ao noicu III I	WIII 13			dan H			
	Printed/Type	su Name			Jignature				N III	vionth	Day	Year	
										200	5		
					1					111	11		

A	NON-HAZARDOUS WASTE MANIFEST	19. Generator ID Number	20. Page	21. Waste Tracking Numb	ber					
	(Continuation Sheet) 22. Generator's Name		2 of 2	ACV	/086223					
	22. Generator's Name HESS PORT READING TERMINAL (COMPANYI CODE 0440) 750 CLIFF ROAD PORT READING, NJ 07064									
	23. Transporter Company Name		U.S. EPA ID Number NT0013812047							
	24. Transporter Company Name	ev Environmenta	U.S. EPA ID Number							
	25. Waste Shipping Name and Description		26. Containe	ers 27. Total Type Quantity						
	5) NON REGULATED MATE	ERIAL	140.	DM	P 27					
	·		X12	5000						
	,									
GENERATOR -										
- GENE										
	29. Special Handling Instructions and Additional Information 5) Profile# 44499 SPENT MET SORB	mation Docu	ument #: D7590	9						
¥	,									
RTER	30. Transporter Acknowledgment of Receipt of Printed/Typed Name	of Materials Signatu	are		Month Day Year					
TRANSPORTER	31. Transporter Acknowledgment of Receipt of	of Materials		2	05012					
TRA	Printed/Typed Name	Signatu	ure		Month Day Year					
ACILITY	32. Discrepancy									
DESIGNATED FACILITY	H141	nero na navana ni superiore								
DESIC										

(C)

FREEEOLD CARPAGE INC

P.O. BOX:5010 • FREEHOLD, NJ:07728-5016 (732) 462-1001 • FAX (732) 308-0924 BILL OF LADING
FCLERA ID MO. NJD054126164

M 406706

St. 9538 Dunham Road 108 Monahan Avenue 132 Nyri Maole Heights, OH 44137 Dunmare: PA 18512 Sumber S

350 Pigeon Point Road New Castle, DE 19720 Phone: (302) 658-2005 Fax: (302) 658-6229 \$20 Beechcraft St. Bartow, FL 33830 Phone: (863) 533-4599 Pax: (863) 533-1613

5533 Dunham Road Maple Heights, OH 44137 Phone: (330) 835-3473 Fax: (330) 835-3732 108 Monahan Avenue Dunmore: PA 18512 Phone: (570) 342-7232 Fax: (570) 342-7367 132 Myrtie Besch Hwy. Sumter, SC 29153 Phone: (803) 773-2611 Pac (803) 773-2942

HESS STATE ST FORT READING, NJ	PHONE (AREA CODE) TRACTOR 7.0.4	TRAILER	APPATIATION OF THE STATE OF THE	
BARTH, FREDERICK COMMENTS OR DELAYS AT SHIPPER Kyle 732-948-998	RE VIII		APRIVAL TIME TOPP EQUIPMENT USED	ATURE TIME
PROPERTY OF THE PROPERTY OF T	U.S. D.C.T. HAZARIOGIS CLASS NA/UH/AND	CONTRACTOR OF SOME	NET UNT CUANTITY MEASURE	WASTE FORM
2 3	14 14	1 pa or on		
SPECIAL HANDLING INSTRUCTIONS INCLUDING SHIPPER'S CERTIFICATION. This is to certify in repreparation according to the applicable regulation named. The consigned can and will accept the ship	if the above named materials are proper of the Department of Transportation	U.S. EPA and the State The materia	a described above were construed	In the Trenorustor
Payment to the contractor for weste removal does not the contractor. PLEASE PRINTI NAME/TITLE Kg / & Young o/b/o / &	d considere payment to the carrier and if the SHIPPER'S SIGN.	e contractor does not pay the carrier,	the shipper is obligated to pay the ag	read rate offered to
CONSIGNEE NAME/ADDRESS CLEAN EARTH OF NJ 115 JACOBUS AVE KEARNY, NJ 07032	PHONE (AREA CODE) TRACTOR 704		FEFORETIMES, IN BASE A	
BARTH, TREDERICK COMMENTS OF DELAYS AT CONSIGNEE	PROCEDURE PROPRIES	335		Y TIAK CHAYE A ME CLUBE TUE
PLEASE PRINT NAME/TITLE	CONSIGNEE SIGN		manari dan katangan peringan	A A
DE DE-HW-203 ME ME-M DE-18W-208 ME-W LL UPW-0190713-OH SH ME UPW-	OPV-2935 ND WH-429		H. W. 11 U VV CRANDA A	

30 m					٠		22	554	98
	NON-HAZARDOUS 1. Generator ID Not Reg		2. Page 1 of	3. Emergency Respons			Tracking Nu	mber	· <u>·</u>
	6. Generator's Name and Mailing Address Hees Corporation Trenton - Mercer Airport 601 Jac West Trenton, NJ 08628	him to the second secon		732-613-1660 Generator's Site Addres 750 Cliff Ro. Port Readin	s (if different t	han mailing add	·	18	l .
	Generator's Phone: 609-406-3069 6. Transporter 1 Company Name Fraehold Cartage, Inc. 7. Transporter 2 Company Name					U.S. EPA ID	105412R	164	
	8. Designated Facility Name and Site Address Clean Earth of North Jersey, Inc. 115 Jacobus Ave Kearny, NJ 07032				alah di katangan dan pangan dan dan dan dan dan dan dan dan dan d	U.S. EPA ID	Number 1991291		
	Facility's Phone: 973-344-4004			,		1			
	9. Waste Shipping Name and Description			10. Conte	alnera	11. Total	12. Unit		
	1. Non RCRA Non DOT Mater	-1		No.	Type	Quantity	Wt.Vol.		
EDATOR	N. 1.			81	CM	est. 18	T		
	2.				**	**			
	3.		<u>.</u>						
	SELECTION OF CONTRACT OF CONTR	And the state of t				4.			
	13. Special Handling Instructions and Additional Info Approval #213081964 - Petroleur AVVT P.O. # 17704-SMT		2,	H DE	ar.	(g)			
	14. GENERATOR'S/OFFEROR'S CERTIFICATION: marked and tabeled/placarded, and are in all resp	I hereby declare that the contents of this creeks in proper condition for transport acco	consignment are	fully and accurately des	cribed above t	y the proper sh	ipping name,	and are classifie	ed, packaged,
¥	Generator a Offeror's Printed/Typed Name	La Herr Coip	Signa		112			Month	Day Year
R INTL	15. Injernational Shipmanis Import to U Transporter Signature (for exports only): 16. Transporter Acknowledgment of Recalpt of Materi		Export from U.S	Port of epi Date leavi	ry/exit: ng U.S.:				
TRANSPORTER	Transporter 1 Printed/Typed Name Transporter 2 Printed/Typed Name	111	Signa Signa	Fred	Ba	h		Month Month	Day Year
^	17. Discrepancy Indication Space Quantity	, Птуре		Residue		Partial Rej	action)		Full Rejection
<u>,</u>	Kor do 150	olby		Manifest Reference N	umber:	Ú.S. EPÀ ID N	•	·	
FACILITY	Facility's Phone:	Received Pending Manife Review/Quality Control D	st ata						*
DESIGNATED	17c. Signature of Alternate Facility (or Genarator)		37.02.33	This property day story and		The street section () and the first	in any or white of the	Month	Day Year
DES	19. Designated Facility Owner or Operator: Certification	n of receipt of materials covered by the m	anliest except a	i noted in Itam 17a					
V	Printsd/Typed Name	MORIASI	Signal					NO I	14 2
169	BLC-0 5 11977 (Rev. 9/09)		· · · · · · · · · · · · · · · · · · ·	į v		· · · · · · · · · · · · · · · · · · ·	and the same of th	TRANS	DOTED 4

GENERATOR HESS

MAN. NO. 17704-1

TRANSPORTERPCY

VEHICLE ID. 0509

DRIVER ON OFF

REMARKS:

01:49 PM 8/19/2021 52400 lb 6

8/19/2021

30900 lb 6

Attachment F

Attachment F Photographic Log 8/18/2021 Tankfield 3 - Stained Stone Removal Area Port Reading Terminal Woodbridge, NJ



Photo 1: Tankfield 3 - Stained stone removal area 8/18/2021 8:44 AM



Photo 2: Tankfield 3 - Stained stone removal area 8/18/2021



Photo 3: Tankfield 3 during stone removal activities - 10:36 AM



Photo 4: Tankfield 3 during stone removal activities

Attachment F Photographic Log 8/18/2021 Tankfield 3 - Stained Stone Removal Area Port Reading Terminal Woodbridge, NJ



Photo 5: Replacement stone installed 1:03 PM



Photo 6: Replacement Stone installation completed.

Attachment F Photographic Log 8/18/2021 Tankfield 3 - Stained Stone Removal Area Port Reading Terminal Woodbridge, NJ



Photo 7: Secured stain stone roll-off